

	Type	Hits	Search Text	DBs
1	BRS	2741	(impact or energy) same (absorber or absorbing) same (member or device) same vehicle	USPAT; EPO; JPO; DERWENT
2	BRS	0	(impact or energy) same (absorber or absorbing) same (member or device) same vehicle same material same annealing	USPAT; EPO; JPO; DERWENT
3	BRS	0	(impact or energy) same (absorber or absorbing) same (member or device) same vehicle same railcar	USPAT; EPO; JPO; DERWENT
4	BRS	0	(impact or energy) same (absorber or absorbing) same (member or frame) same vehicle same railcar	USPAT; EPO; JPO; DERWENT
5	BRS	2540	(impact or energy) same (absorber or absorbing) same (member or frame) same vehicle	USPAT; EPO; JPO; DERWENT
6	BRS	4	(impact or energy) same (absorber or absorbing) same (member or frame) same vehicle same underframe	USPAT; EPO; JPO; DERWENT
7	BRS	12	(impact or energy) same (absorber or absorbing) same (member or device) same annealing	USPAT; EPO; JPO; DERWENT
8	BRS	2	(impact or energy) same (absorber or absorbing) same (member or device) same (steel or aluminum) same annealing	USPAT; EPO; JPO; DERWENT
9	BRS	834	(impact or energy) same (absorber or absorbing) same (member or device) same (steel or aluminum)	USPAT; EPO; JPO; DERWENT
10	BRS	125	(impact or energy) same (absorber or absorbing) same (member or device) same (steel or aluminum) same vehicle	USPAT; EPO; JPO; DERWENT
11	BRS	0	vehicle same frame same material same (softening or soften) same annealing	USPAT; EPO; JPO; DERWENT
12	BRS	0	vehicle same frame same material same (softening or softened) same annealing	USPAT; EPO; JPO; DERWENT
13	BRS	174	material same (softening or softened) same process same annealing	USPAT; EPO; JPO; DERWENT
14	BRS	46	material same (steel or aluminum) same (softening or softened) same process same annealing	USPAT; EPO; JPO; DERWENT

	Time Stamp	C m me n t s	Err or De fin iti on	Err r s
1	2003/09/19 12:44			0
2	2003/09/19 12:40			0
3	2003/09/19 12:41			0
4	2003/09/19 12:41			0
5	2003/09/19 12:43			0
6	2003/09/19 12:43			0
7	2003/09/19 12:45			0
8	2003/09/19 12:46			0
9	2003/09/19 12:46			0
10	2003/09/19 12:51			0
11	2003/09/19 12:52			0
12	2003/09/19 12:52			0
13	2003/09/19 12:55			0
14	2003/09/19 12:55			0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
1	BRS	L1	472	188/377	USPAT; EPO; JPO; DERWENT	2003/09/19 15:30			0
2	BRS	L2	838	296/189	USPAT; EPO; JPO; DERWENT	2003/09/19 15:31			0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Com me nt s	Error De fin iti on	Error s
1	BRS	L2	838	296/189	USPAT; EPO; JPO; DERWENT	2003/09/19 15:31			0
2	BRS	L1	472	188/377	USPAT; EPO; JPO; DERWENT	2003/09/19 15:34			0
3	BRS	L4	0	(frame or member) same (soften or softening) same (anneal or annealing) same vehicle	USPAT; EPO; JPO; DERWENT	2003/09/19 15:35			0
4	BRS	L3	105	(frame or member) same (soften or softening) same (anneal or annealing)	USPAT; EPO; JPO; DERWENT	2003/09/19 15:35			0